

PROJECT PHOTO REPORT
Union County Community Center



Date: Week Ending July 31st 2011

Client: Union County

Project Name: Union County Community Center

Project Number: 10-071

Submitted By: Winter Construction

Comments: July 25th through July 31st Construction Progress Photos



Main entrance progress view



Stucco and windows at arch opening



North stairs wall framing



Front entrance exterior stone



Cementitious underlayment at stucco application



Soffit framing at community room



Insulation and protection at walk-in Freezer and Cooler floor prep



Electrical Box Installation

THIS WEEK'S ACTIVITIES	NEXT WEEK'S ACTIVITIES
<ul style="list-style-type: none"> - Exterior Stone Installation - Exterior cast stone - 2nd Floor MEP Rough-in - Stucco Installation - Drywall - Exterior stair wall framing - In-wall Insulation - Walk-in Cooler/Freezer Installation 	<ul style="list-style-type: none"> - Exterior cast stone - 2nd Floor MEP Rough-in - Stucco Installation - Drywall - In-wall insulation - Site utilities - Folding glass partitions - Exterior sitework - Site utilities - Layout curb and gutter